

City Manager's Monthly Report

Dams Reconstruction Project

Completed Downstream MIP
Platform Construction



MIP Drill Installing Test
Panel on Platform



City Manager's Monthly Report

Dams Reconstruction Project

Principle
Spillway
Excavation Site
Overview



City Manager's Monthly Report

Dams Reconstruction Project

Working After
Dark



City Manager's Monthly Report

Dams Reconstruction Project



**Added 2nd
Cement Silo to
Increase Plant
Capacity**

City Manager's Monthly Report

Dams Reconstruction Project

Drilling Deep De-Watering Wells



The CMS (Cutter Soil Mixer) Drill



City Manager's Monthly Report

Dams Reconstruction Project

Excavating the Spillway Base



Excavating MIP Test Panels
For Core Samples



City Manager's Monthly Report

Dams Reconstruction Project

Loading
Excavated
Spoil for
Removal



City Manager's Monthly Report

Dams Reconstruction Project

The Bypass
Canal after 6.5
inches of rain



City Manager's Monthly Report

Dams Reconstruction Project

The Schnabel
Test Lab (old
PD building)



City Manager's Monthly Report

Dams Reconstruction Project

Staging The
De-Watering
System Trunk
Line

